


DRAGLINE INSPECTION SERVICE



National Plastics & Rubber is proud to offer a dragline inspection service.

HOW DOES IT WORK?

As each dragline is different, our knowledgeable team will inspect a dragline on site and provide a detailed report based on that dragline's condition. Each report is uniquely tailored to that dragline, ensuring only relevant parts & products are recommended.

NPR has developed a range of products designed to increase the service life of each dragline, reduce machine downtime, and minimise WHS risks.

WHAT PRODUCTS DOES NPR OFFER?

We design and manufacture plastic, rubber and polyurethane products to suit every area of your dragline.

While our team will provide you with a complete guide to each individual dragline, if you would like more information on our range of dragline products contact us on:


07 3279 3066 | sales@nationalplastics.net.au

- 1 SHOE AREA**
- 2 TUB SCRAPERS**
- 3 CABLE FEEDER ROLLERS**
- 4 FAIRLEADS**
- 5 DRAG CHUTE**
- 6 HOIST ROPE APERTURE**
- 7 TRI-STRUCTURE & MAST**
- 8 BOOM AREA**
- 9 SWING MOTOR COMPONENTS**
- 10 LACING PROTECTORS**
- 11 DYNA VEINS**


DRAGLINE INSPECTION SERVICE

EXAMPLE DRAGLINE INSPECTION REPORT


Provided below are example pages from a recent dragline report to demonstrate what you can expect from a National Plastics & Rubber dragline inspection.




Lacing Protector	
Part No.	NPR01259
Material No.	N/A




Mounting Bracket	
Part No.	NPR01734-00
Material No.	N/A




Shaft Bracket	
Part No.	NPR00995-00
Material No.	N/A




Shaft	
Part No.	NPR01105-00
Material No.	N/A







Compression Element	
Part No.	NPR01749-00
Material No.	N/A




Bearingless Roller (Outer)	
Part No.	NPR00555-00
Material No.	N/A



Bearingless Roller (Centre)	
Part No.	NPR00008-00
Material No.	N/A




Collar	
Part No.	NPR00786-00
Material No.	N/A





Wear Pad	
Part No.	NPR06518-03
Material No.	N/A

Part No.	NPR06518-00
Material No.	N/A

DESCRIPTION	PART NO	Material No.
<p>Propel Shoe Pad</p> 	NPR01095-00	N/A

Current System





Proposed Upgrade

Colours for reference only
All blocks are black

The current system you have uses timbers which are bolted in to position. These timbers have worn and snapped and haven't been replaced.